

Owners Notes to Property Inspection

Broken cover plate on outlet (page 8)

Cover plate has been replaced.

Exposed wires in closet (page 11)

These wires are for the installation of an alarm system. They have no current running through them.

Cover plate has been installed.

Construction debris in crawl space (page 13)

Crawl place has been cleaned.